



March 6, 2012

UPTOWN CAMPUS

**Building Location: Eastman Tower, Exterior**

**Eastman, Stuyvesant, Mohawk & Livingston Towers,  
Exterior Survey & Design**

Project / Work Order #: **P-0374**

ESTIMATED START: **3/9/2012 6:00 PM**  
ESTIMATED END: **3/18/2012 11:00 AM**

**Project Description / Scope:**

Survey exterior of Eastman, Stuyvesant, Mohawk and Livingston Towers for structural damage and leakage. Survey will require hydraulic scaffolding on all four sides of each building. Provide design drawings as necessary. Bid and administer subsequent projects as necessary.

POTENTIAL IMPACT ON SURROUNDING AREAS: (please check all that apply)

- |   |  |  |
|---|--|--|
| <input checked="" type="checkbox"/> Change in access/egress | <input type="checkbox"/> Odor                            | <input type="checkbox"/> Hot Water     |
| <input checked="" type="checkbox"/> Dust                    | <input type="checkbox"/> Traffic                         | <input type="checkbox"/> Rest Rooms    |
| <input checked="" type="checkbox"/> Noise                   | <input type="checkbox"/> Water/Sewer                     | <input type="checkbox"/> Elevator      |
| <input type="checkbox"/> Ventilation                        | <input type="checkbox"/> Parking                         | <input type="checkbox"/> Fire Alarm(s) |
| <input type="checkbox"/> Heating/Cooling                    | <input type="checkbox"/> Other: surveyors outside window |  |

**CONTACT INFORMATION:**

If you have any questions or concerns regarding this work, please contact the project manager, Dave Ono, at [dono@albany.edu](mailto:dono@albany.edu) or at **442-3403**.

For a listing of all current Project Work Alert Notification and notable campus projects, please view our web page at [www.albany.edu/facilities](http://www.albany.edu/facilities)

***We apologize for any inconvenience this work may cause as we continue to renovate and upgrade the University; and we thank you in advance for your cooperation.***